Drawings

A replacement sheet for figure 10 is attached hereto.

10/707524

2 of 3

HSJ920040074US2

RECEIVED CENTRAL FAX CENTER MAY 0 8 2007

Remarks

The replacement sheet for figure 10 attached hereto corrects a typographical error in the figure. In the drawing as filed reference numeral "42B" was incorrectly used where "51" should have been used. The replacement sheet, therefore, shows the uppermost feature in figure 10 as "51." This change brings figure 10 into accord with figures 3, 8 and 9 inter alia and the specification which describes "51" as the body of the pole piece. (See, for example, p. 7, line 22).

Respectfully submitted,

G. Marlin Knight (Reg. Number 33,409)

(customer no. 000041482)

A. Malin Knight

PO Box 1320

Pioneer, CA 95666

209-295-1982